



Engine Chassis Service

Job No: MWJ101598

CUSTOMER COPY



www.bristolcaravans.com

Booking Date: 04 Mar 2021
Customer Name: Mr BLANK
Vin Number: ZY1SA61AMLDT04145



Vehicle Description:

ADRIA ADORA 613 DT ISONZO
0.0L LPG 2020 Caravan
Mileage:

Checks

Check	Result
1 Paint and bodywork for damage and corrosion	Satisfactory
2 Side door check-strap/hinges & grease	Satisfactory
3 Lights: External & Cab	Satisfactory
4 Key fob battery check - radio frequency check	Satisfactory
5 Horn	Satisfactory
6 Instruments	Satisfactory
7 Airbags for visible damage	Satisfactory
8 Breakdown kit fitted	Satisfactory
9 Wiper Blades	Satisfactory
10 Washers, top up fluid if required	Satisfactory
11 Engine and engine compartment for leaks	Satisfactory
12 Condition of visible drive belts	Satisfactory
13 Coolant level, top up if required, Anti-freeze: Record strength	Anti-freeze protects to (degrees C):: 0
14 Power-assisted steering oil level, top up if required	Satisfactory
15 Brake fluid: record condition / water content	Satisfactory
16 Brake fluid level, top up if required	Satisfactory
17 ATF level (automatic), top up if required	Satisfactory
18 Engine battery: Check/Load Test/Top up	Satisfactory
19 Idle speed	Satisfactory
20 Thickness of front brake pads/linings	Satisfactory
21 Condition of front brake discs or drums	Satisfactory
22 Front wheel bearings, for wear & seal leaks	Satisfactory
23 Steering joints and boots for wear and damage	Satisfactory
24 Front suspension joints/bushes	Satisfactory
25 Drive shafts, CV boots	Satisfactory
26 Gearbox/final drive/rear axle for leaks and damage	Satisfactory
27 Manual gearbox oil level, top up if required	Satisfactory
28 ABS sensor and cables	Satisfactory
29 Brake system for leaks and damage	Satisfactory
30 Thickness of rear brake pads/linings	Satisfactory

31	Condition of rear brake discs or drums	Satisfactory	●
32	Rear wheel bearings, for wear & seal leaks	Satisfactory	●
33	Rear suspension joints/bushes	Satisfactory	●
34	Rear axle oil level or Grease AL-KO Chassis	Satisfactory	
35	Underbody sealant and chassis for damage	Satisfactory	●
36	Condition of the exhaust inc. mountings	Satisfactory	●
37	Trailer 12N / 12S or 13 pin 12v sockets	Satisfactory	●
38	Renew engine oil and filter	Satisfactory	●
39	Renew the air filter	Satisfactory	●
40	Renew spark plugs (petrol)	Satisfactory	●
41	Renew the fuel filter	Satisfactory	●
42	Engine basic settings, OBD check/report	Satisfactory	●
43	Road Test	Green	●

Observations

Check	Result
44 Camshaft belt, confirm next replacement date	Date:: 0/0/0 ●
45 Tyre tread depths	NSF: 0 , OSF: 0 , NSR: 0 , OSR: 0 ●
46 Tyre pressures	NSF: 0 , OSF: 0 , NSR: 0 , OSR: 0 ●
47 Tyre age	NSF: 0 , OSF: 0 , NSR: 0 , OSR: 0 ●
48 Engine battery, Voltage at rest	Voltage:: 0 ●
49 Alternator output	Voltage:: 0 ●

Important

Check	Result
50 This service report only relates to the condition of the above mentioned vehicle at the time of completion of the service. It should not be regarded as evidence of the condition of the items at any other time.	